

APEX LIFT SERVICES

DAILY FORKLIFT SAFETY INSPECTION

REPORT FL-260828-17

ASSET

Atlas FL-25 / FKL-204

LOCATION

Warehouse A / Loading Bay 3

INSPECTION DATE

August 28, 2026

TECHNICIAN

Maya Chen

NEEDS ATTENTION

CHECKPOINT	RESULT	OBSERVATION	ACTION
Forks and carriage	PASS	No visible cracks	Continue service
Service brake	PASS	Stops within limit	Continue service
Backup alarm	FAIL	Alarm is intermittent	Replace before next shift
Right front tire	WARN	Tread is near limit	Replace within 14 days

PRIORITY FINDINGS

- HIGH

Backup alarm - replace alarm module before the next operating shift.
- MEDIUM

Right front tire - schedule replacement within 14 days.